F18#2 ACT/015/032



DIVISION OF CIL. GAS & MINING **S**EarthFax

EarthFax
Engineering Inc.
Engineers/Scientists
7324 South 1300 East
Suite 100
Midvale, Utah 84047
Telephone 801:561-1555

Mr. Lowell P. Braxton Utah Division of Oil, Gas & Mining 355 West North Temple 3 Triad Center Suite 350 Salt Lake City, Utah 84180-1203

Subject: Crandall Canyon Mine Cut and Fill

Calculations

Dear Lowell:

March 3, 1989

Pursuant to comment UMC 817.101 issued to Genwal Coal Company on October 19, 1988, we herewith submit revised mass balance calculations for reclamation of the Crandall Canyon Mine (ACT/015/032). These revisions are in the form of a revised Item 3-12 and Revised Plates 3-4, 3-5, and 3-5a.

Following revision of the mass balance calculations, the bond estimate has remained unchanged (see Item 3-12). Please contact us if you have any questions.

Sincerely,

Richard B. White, P.E.

Richard B. White

Principal Hydrologist

Enclosures

cc: Andy King